


ACCEPT SQ-OFF FL-OFF PR-OFF  contact File Dynamics USA with your questions tel USA - 216 - 831- 6131 fax USA - 216 - 831- 0916	VMX= 4.0 FMX= 62 AMX= 139 EMX= 0.2 MEX= 121 FVP= 1.00 ACCELEROMETER CALIBRATION N.I.S.T. Traceable SERIAL NUMBER: <u>16216</u> CALIBRATION FACTOR: <u>1000 Gw</u> PAK (*5000) DATE: <u>02-OCT-13</u> PDA OPERATOR: <u>[Signature]</u> OP: alex [ver:4.05]
---	---

<-AT:PIEZORESISTIVE

AT:PIEZOELECTRIC->