


ACCEPT SQ-OFF FL-OFF PR-OFF  contact Pile Dynamics USA with your questions tel USA - 216 - 831- 6131 fax USA - 216 - 831- 0916	VMX= 4.4 FMX= 68 AMX= 139 EMX= 0.3 MEX= 133 FUP= 1.00 ACCELEROMETER CALIBRATION N.I.S.T. Traceable SERIAL NUMBER: 11145 CALIBRATION FACTOR: 1040 GIV PAK ←*5000: _____ DATE: 28-May-04 PDA OPERATOR: Fred Housain ←-AT:PIEZORESISTIVE OP: FRED [ver:4.05] [AT:PIEZOELECTRIC]→
---	--