



ACCEPT SQ-OFF FL-OFF PR-OFF	VMX= 4.2	FMX= 64	AMX= 149
	EMX= 0.3	MEX= 125	FUP= 0.99



contact File Dynamics USA  
with your questions  
tel USA - 216 - 831- 6131  
fax USA - 216 - 831- 0916

ACCELEROMETER CALIBRATION N.I.S.T. Traceable  
SERIAL NUMBER: 11263  
CALIBRATION FACTOR: 1030 6V  
PAK < \*5000 > : DATE: 24-May-07  
PDA OPERATOR: *Alex*

<-AT:PIEZORESISTIVE

OP: alex [ver:4.05]

AT:PIEZOELECTRIC->