


ACCEPT SQ-OFF FL-OFF PR-OFF  contact File Dynamics USA with your questions tel USA - 216 - 831- 6131 fax USA - 216 - 831- 0916	UMX= 4.6 FMX= 71 AMX= 159 EMX= 0.3 MEX= 139 FVP= 1.00 ACCELEROMETER CALIBRATION N.I.S.T. Traceable SERIAL NUMBER: 11402 CALIBRATION FACTOR: 1040 G/V PAK (5000): _____ DATE: 02-Aug-04 PDA OPERATOR: Fred Hussin
---	--

<-AT:PIEZORESISTIVE

OP: FRED [ver:4.05]

AT:PIEZOELECTRIC->