


ACCEPT SQ-OFF FL-OFF PR-OFF



contact Pile Dynamics USA  
with your questions  
tel USA - 216 - 831- 6131  
fax USA - 216 - 831- 0916

UMX= 4.0 FMX= 61 AMX= 159  
EMX= 0.2 MEX= 119 FUP= 1.01  
ACCELEROMETER CALIBRATION N.I.S.T. Traceable  
SERIAL NUMBER: 11413  
CALIBRATION FACTOR: 1080 G/V  
PAK (\*5000): \_\_\_\_\_ DATE: 10-DEC-10  
PDA OPERATOR: *Alex*  
<-AT:PIEZORESISTIVE OP: alex [ver:4.05] AT:PIEZOELECTRIC->