



ACCEPT SQ-OFF FL-OFF PR-OFF contact Pile Dynamics USA with your questions tel USA - 216 - 831- 6131 fax USA - 216 - 831- 0916	VMX= 3.4 FMX= 54 AMX= 110 EMX= 0.2 MEX= 105 FUP= 1.01 ACCELEROMETER CALIBRATION N.I.S.T. Traceable SERIAL NUMBER: <u>11515</u> CALIBRATION FACTOR: <u>1012 G/Y</u> PAK <#5888> _____ DATE: <u>30 Sept. 04</u> PDA OPERATOR: <u>[Signature]</u> <-AT:PIEZORESISTIVE OP: DAUE [ver:4.05] AT:PIEZORESISTIVE->
--	---