


ACCEPT SQ-OFF FL-OFF PR-OFF	VMX= 4.5	FMX= 70	AMX= 120
	EMX= 0.3	MEX= 137	FUP= 1.02



contact File Dynamics USA
with your questions
tel USA - 216 - 831- 6131
fax USA - 216 - 831- 0916

ACCELEROMETER CALIBRATION N.I.S.T. Traceable
SERIAL NUMBER: 11841
CALIBRATION FACTOR: 1080 %
PAK (*5000): _____ DATE: 9 OCT 17
PDA OPERATOR: *[Signature]*