


OBTA: ON [ALT-F1/BB=60]

File Dynamics, Inc.

DPF



<input type="checkbox"/> ACCEPT <input type="checkbox"/> SQ-OFF <input type="checkbox"/> FL-OFF <input type="checkbox"/> PR-OFF	UMX= 4.9 FMX= 77 AMX= 169 EMX= 0.4 MEX= 150 FVP= 0.99
	ACCELEROMETER CALIBRATION N.I.S.T. Traceable SERIAL NUMBER: <u>16183</u> CALIBRATION FACTOR: <u>1035%</u> PAK (*5000): _____ DATE: <u>11 July 16</u> PDA OPERATOR: <u>[Signature]</u>
<p>contact Pie Dynamics USA with your questions tel USA - 216 - 831- 6131 fax USA - 216 - 831- 0916</p>	←-AT:PIEZORESISTIVE OP: laine [ver:4.05] AT:PIEZOELECTRIC →