


ACCEPT SQ-OFF FL-OFF PR-OFF	UMX= 5.0	FMX= 71	AMX= 159
	EMX= 0.3	MEX= 139	FUP= 1.00
	ACCELEROMETER CALIBRATION		N.I.S.T. Traceable
contact File Dynamics USA with your questions	SERIAL NUMBER:	10359	
tel USA - 216 - 831- 6131	CALIBRATION FACTOR:	895 %	
fax USA - 216 - 831- 0916	PAK (*5000):	DATE: 16 MAR 16	
	PDA OPERATOR:	<i>[Signature]</i>	