


ACCEPT SQ-OFF FL-OFF PR-OFF  contact Pile Dynamics USA with your questions tel USA - 216 - 831- 6131 fax USA - 216 - 831- 0916	UMX= 3.3 FMX= 52 AMX= 110 EMX= 0.2 MEX= 101 FUP= 1.00 ACCELEROMETER CALIBRATION N.I.S.T. Traceable SERIAL NUMBER: 11050 CALIBRATION FACTOR: 995 G/V PAK <X5000>: DATE: 27 Apr. 04 PDA OPERATOR: <i>[Signature]</i> OP: fred [ver:4.05]
---	---

<-AT:PIEZORESISTIVE

AT:PIEZOELECTRIC->